

## Customer Assembly Instruction

Seite / Page  
1 / 2

**Number:**



**M-260**

**Nummer:**

**Description:**


**4.3-10-Flange mount cable jack**

**Beschreibung:**




### Recommended Soldering Process

Inductive soldering



### Cable Stripping Dimension

Cable: UT-216  
Flexiform 401SL HFJ



Rev.:  
1

Date:  
03.11.2014

Signature:  
R.Schwär

Alteration:  
Modification

Approved:

## Customer Assembly Instruction

Seite / Page  
2 / 2

**Number:**

**M-260**

**Nummer:**

**Description:**


**4.3-10-Flange mount cable jack**

**Beschreibung:**

### Soldering Set-up

Inductor position:

Dimension A: 5,5mm  
Dimension B: 11,95mm  
Dimension C: 23,15mm



### Soldering Parameter

TBD

### Notes

### Aufzeichnungen

While the information has been carefully compiled to the best of our knowledge, nothing is intended as representation or warranty on our part and no statement herein shall be construed as recommendation to infringe existing patents. In the effort to improve our products, we reserve the right to make changes judged to be necessary.

Rev.:  
1

Date:  
03.11.2014

Signature:  
R.Schwär

Alteration:  
Modification

Approved: