

Customer Assembly Instruction

Seite / Page
1 / 2

Number:


M-261

Nummer:

Description:

4.3-10-Flange mount cable jack


Beschreibung:



Recommended Soldering Process


Inductive soldering

Flange mount
cable jack



Cable Stripping Dimension

Cable: UT-141; Flexiform 402



Rev.:
2

Date:
03.12.2014

Signature:
R.Schwär

Alteration:
Modification

Approved:

Customer Assembly Instruction

Seite / Page
 2 / 2

Number:

M-261

Nummer:

Description:

4.3-10-Flange mount cable jack

Beschreibung:


Soldering Set-up

Inductor position:

Dimension A: XXXXmm

Dimension B: XXXXmm

Dimension C: XXXXmm



Soldering Parameter

TBD

Notes

Aufzeichnungen

While the information has been carefully compiled to the best of our knowledge, nothing is intended as representation or warranty on our part and no statement herein shall be construed as recommendation to infringe existing patents. In the effort to improve our products, we reserve the right to make changes judged to be necessary.

Rev.:
 2

Date:
 03.12.2014

Signature:
 R.Schwär

Alteration:
 Modification

Approved: